



## Zinc Nitrate 50% Solution

### PHYSICAL PROPERTIES

Assay As ZnNO<sub>3</sub>2  
Assay as Zn  
pH @ 15° C  
Specific Gravity @ 15° C  
Color

### SPECIFICATION

50% Minimum  
17% Minimum  
2.6 – 3.0  
1.581 – 1.587  
< ALPA 40 – Clear, colorless solution

### IMPURITIES

Insolubles  
Iron  
Heavy metals (as Pb)

### TYPICAL ANALYSIS

< 0.01%  
< 50 ppm  
< 0.01%

NOTE: Impurities levels are based on historical data and not routinely reported on COA.

Uses: Catalysts for resin polymerization, coagulant in latex dipping, manufacture of rust proofing agents, mordant, fountain solution ingredient and as a source of zinc ion for phosphating and other metal finishing solutions.

Shipping Location: 5910 Pharr Mill Road  
Harrisburg, NC 28075  
704-455-5181 Phone  
704-455-5987 Fax

Containers: Drums and Tank Trucks